Qty:

User:

Tuesday, 5/23/2006 8:12:37 AM

Kim Johnston

Process Sheet

Customer **Job Number** : CU-DAR001 Dart Helicopters Services

Type

: 27160B

Estimate Number

: 11274

P.O. Number

This Issue

Prsht Rev.

First Issue

Al4:

: 5/23/2006

: NC : N/A

: 26878B

S.O. No. : NA

: LARGE FAB ASSY

Drawing Name

: 206L BASKET LID

: D2252043 **Part Number**

: D2252 **Drawing Number** : N/A

Project Number **Drawing Revision**

Material Due Date

: 6/6/2006

1 Um:

Each

Previous Run Written By

Checked & Approved By

Comment

REVISED AS PER REV E 05-12-06 JLM : Est Rev:I

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 M304TS0750W065 304 SQ Tube.75x.75x.065W



Comment: Qty.:

32.5539 f(s)/Unit Total:

32.5539 f(s)

H100183-> C-BPTOOIH H100583

3/4" x 3/4" x 0.063 wall 304/316 SS tubing.

Batch: 1100704 -> 25.5"

2.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1- Cut D2252-1-3-9 as per Dwg D2252

2-Drill hole in D2252-1 as per Dwg D2252

3-Deburr & Remove all Markings from Material

DD

06-05-29

3.0

D2329

Label Plate



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

1 D2329 Label Plate BAZYMO

06-04-08

4.0

D23271

Spacer Bushing

Comment: Qty.:

1.0000 Each(s)/Unit Total:

Bushing

1.0000 Each(s)

Pick:

Qty Part Number 1 D2327-1

Description

Batch

Babiya

06.06.03

20

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE			Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector		
							<u> </u>			
* * * * * *	30	•						3		
						ļ				
. .	·									
,	***							- Jan		

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
	·	Description of NC		Corrective Action Section B	Verification	Approval Design Mgr	Ammercal			
DATE	STEP	Section A	Initial Design Mgr	Action Description Sign & Date	Section C		Approval QC Inspector			
				'						
)								
			-		:					
	<u> </u>		4							
		:								
							. "			
				·	:	d s cart				
•						andria Salah di Julya Liberah				

Part No:	PAR #:	Fault Category:	NCR:	Yes No DQA:	Date:
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

Tuesday, 5/23/2006 8:12:38 AM Date: User: Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: 206L BASKET LID Job Number: 27160B Part Number: D2252043 Job Number: Seq. #: **Machine Or Operation:** Description: Hinge 5.0 D22321 Comment: Qty.: 2.0000 Each(s) 2.0000 Each(s)/Unit Total: Pick: **Qtv Part Number** Description Batch **625238** 2 D2232-1 HINGE 06-06-08 D2581 Mounting Bracket Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description Batch Mounting Chanel B26204 D 2 D2581 7.0 M304EX07516F Expanded Metal Flat Stai Comment: Qty.: 18.9000 sf(s)/Unit Total: 18.9000 sf(s) Pick: **Qty Part Number** Description Batch 18 sf M304EX0.75-16F Expanded Metal H100981 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 8.0 Comment: LARGE FABRICATION RESOURCE 1 1-Weld as per Dwg D2252 using Welding Table and corner Jig Deburr as required Batch: M100 5a 7 A/R SS ROD Op-0P-08 9.0 QC5/9 WELD INSPECTION Comment: WELD INSPECTION POWDER COATING POWDER COATING 10.0 Comment: POWDER COATING DC Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector			
NOD.		WORK ORDER NON-CONF	OPMANCE (NC	D)	<u> </u>		1			

NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
 	T	Description of NC		Corrective Action Section B			Annuoval	A			
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector			
		·									
		,									
						:					
							J.				
	<u></u>										

Part No:	PAR #:	Fault Category:NCR	Ye	No DQA:	Date: 06/06/2
NOTE: Date & initial all entries			QA	: N/C Closed:	Date:

Date:

Tuesday, 5/23/2006 8:12:38 AM

User:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 206L BASKET LID

Job Number: 27160B

Part Number: D2252043

Job Number:



Seq. #:

Machine Or Operation:

Description:

11.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION



12.0

PACKAGING RESOURCE #1





Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

527160

13.0

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Inspection Level 21

Job Completion



JOC/02/23

Dart Aerospace Ltd


W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector				
					_						

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC	Corrective Action Section B			Verification	Approval	Annroval		
DATE	STEP	Section A			Sign & Date	Section C	Design Mgr	Approval QC Inspector		
	-							:		
						·				

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries				QA:	N/C C	losed:	Date:




DESIG	м КЕ	DRAWN BY MB	DART AEROSPACE LTD
CHECKED APPROVED		L	HAWKESBURY, ONTARIO, CANADA DRAWING NO. REV. E
	*	-tt	D2252 SHEET 1 OF 5
DATE			TITLE SCALE.
05.1	1.10		BASKET ASSEMBLY (206L) NTS
С		95.12.11	RE-DRAWN
D		99.09.14	MODIFIED LATCH, D2581 WAS D2255-3
Ε		05.11.10	D2253-1 WAS D2253 (NCR 533),
			ADDED MEMBERS TO LID FRAME,
		:	ADDED D2232-1/-3 & D2252-19



Qty -041	Qty -043	Part Number	Description	L	A
Х		D2252-041	BASKET ASSEMBLY		
	X	D2252-043	LID ASSEMBLY		
	2	D2232-1	HINGE		
2		D2232-3	HINGE		
5		D2235-1	RIB		
2	2	D2252-1	FRAME	25.50	45
2		D2252-3	FRAME	96.00	45
	2	D2252-7	FRAME	24.00	90
1		D2252-9	FRAME	10.25	90
1		D2252-11	FRAME	25.00	90
1		D2252-13	FRAME	42.00	90
1		D2252-15	FRAME	15.00	90
4		D2252-17	FRAME	19.78	53
	2	D2252-19	FRAME	95.27	45
	2	D2252-21	FRAME	30.82	90
	1	D2252-23	FRAME	30.62	90
2		D2253-1	LUG		
2		D2254	GUSSET		
	1	D2327-1	BUSHING		
1		D2327-3	BUSHING		
	1	D2329	LABEL PLATE		
4	2	D2581	MOUNTING CHANNEL		
A/R	A/R		3/4-16F EXPANDED METAL		

NOTES:

- MATERIAL: AISI 304/316 SS 3/4 X 3/4 X 0.060 WALL SQUARE TUBE (REF. DART SPEC. M304TS0.750W.060)
- 2. FINISH: POWDER COAT ASSEMBLY GLOSS WHITE (4.3.5.2) PER DART QSI 005 4.3
- 3. WELD PER DART QSI 004
- 4. ALL DIMENSION ARE IN INCHES
- 5. TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.



SHOP COPY

RETURN TO

ENGINEERING

UNCONTROLLED COPY

SUBJECT TO AMENDMENT


WITHOUT NOTICE


WORK ORDER NO 27160B

Copyright @ 1994 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

e de la companya de	The state of the s	
*		
; '	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
·		
· · · · ·		:
		;
		•
• :		,
f.		
•		
* *		
.		
/ -		
		•
<u>.</u>		
•		
	mental as as in Library and the last	





MESH D2329 LABEL PLATE (REF) 0 SECTION G-G SKIN WITH 3/4-16 F EXPANDED SS, TACK WELD EACH STRAND END TO FRAME

8

SHOP COPY RETURN TO

BJECT TO AMENDMENT ENGINEERING ONTROLLED COPY WITHOUT NOTICE

Q

Copyright © 1994 by DART AEROSPACE LTD

PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

A N

PURPOSE

ဓ္က


COPIED

THIS DOCUMENT IS

D2329 LABEL PLATE CENTER ON THE

BASKET LID

	in the second			
		사람이 가게 되었다. 이번 보고 있는데 보고 있는데 보고 있다. 		
				·
	: :-			
	s' •		·	
	j			
				· · · · · · · · · · · · · · · · · · ·
				î.
•		다 한 마시 가는 사람들을 통해 되었다. 		
4.	·세탁 - 세			
	grå.			
	ें भा । -			
1				
	•			
ý.				
	÷.			
1				
	ağ r			
	•			
÷				
•				
,				
	e de la companya de l	the second of th		
		and the second of the second o		



				Na Caraca de Car	
					is the second
1					•
4					
· · ·				r.	å
					8
1					
		•	man (1944)		
			~*·		
					ing in the second of the seco
	See See See				
				•	
•					
•					
					į
f. Santa					
					,
					,
		•			
					. 4
•					
	a de la companya della companya della companya de la companya della companya dell				·
■ 1 mm = 1 ident	the state of the s				4.0